
roini approved REPORT DOCUMENTATION PAGE OMB No. 0704-0188 Public reporting burden for this collection of information is estimated to average 1 hour per response including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for information Operations and Reports 1215 Jefferson Craris high way, Suite 1204. Artificiation, v.E. 22202-4302, and to the Office of Management and Budge*, Paperwork Reduction Project (0704-0188), Washington, DC 20503. 1. AGENCY USE ONLY (Leave blank) 2. REPORT DATE 3. REPORT TYPE AND DATES COVERED August 1994 Final Report 4. TITLE AND SUBTITLE S. FUNDING NUMBERS Partial Airfield Evaluation Pueblo Memorial Airport, Pueblo, Colorado 6. AUTHOR(S) Lt Col George E. Walrond, P.E. SSqt Simon A. Cox MSgt Ralph E. Crompton SSqt Michael G. Geer 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) 8. PERFORMING ORGANIZATION REPORT NUMBER HQ Air Force Civil Engineer Support Agency 139 Barnes Drive Suite 1 Tyndall AFB FL 32403-5319 9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) 10. SPONSORING / MONITORING AGENCY REPORT NUMBER 302 Airlift Wing 295 Dover Street Suite 104 Peterson AFB CO 80914-8030 11. SUPPLEMENTARY NOTES 12b. DISTRIBUTION CODE 12a. DISTRIBUTION: AVAILABILITY STATEMENT Distribution unlimited. 13. ABSTRACT (Maximum 200 words) At the request of the 302 AW (AFRES) a pavement evaluation team from HQ Air Force Civil Engineer Support Agency (HQ AFCESA) did a partial evaluation of the Pueblo, Colorado municipal airport. The objective of the evaluation was to determine if the now closed Runway 12/30 is suitable for C-130 assault operations. The evaluation was done on 5-7 April 1994. The runway pavement has failed and is structurally weak. Severe block cracking, alligator cracking, heaving, and rutting is prevalent. The runway is not suitable for C-130 assault operations and would have to be reconstructed to accommodate this mission.

15. NUMBER OF PAGES 34. SUBJECT TERMS Pavement Classification Number Airfield Pavements 16. PRICE CODE **Electronic Cone Penetrometer** Airfield Pavement Evaluation Dynamic Cone Penetrometer Allowable Gross Loads 19. SECURITY CLASSIFICATION 20. LIMITATION OF ABSTRACT 17. SECURITY CLASSIFICATION SECURITY CLASSIFICATION OF THIS PAGE OF ABSTRACT OF REPORT UNCLASSIFIED UNCLASSIFIED UNCLASSIPIED

NSN 7540-01-280-5500

Standard Form 298 (Rev. 2-89)
Prescribed by ANSI Std. 239-18
298-102

Best Available Copy



TEAM PHOTO WITH THE CONTINGENGY VAN : LEFT TO RIGHT LT. COL. WALROND, CAPT. BOSWORTH, SSgt. COX, SSgt. GEER, Mr. CHAMBERLIN, Mr. SIKES, MSgt. CROMPTON.

Accesio	n For	1			
NTIS DTIC Unanno Justific	TAB ounced	7 1 10 10			
By	By				
Availability Codes					
Dist	Avail and Specia	•			
A-1					

TABLE OF CONTENTS

		Page
EXECUTIVE SU	MMARY	iii
SECTION I:	INTRODUCTION	1
SECTION II:	BACKGROUND DATA	2
SECTION III:	TEST PROCEDURES	4
SECTION IV:	METHODOLOGY OF ANALYSIS	6
SECTION V:	PAVEMENT ASSESSMENT	9
SECTION VI:	CONCLUSIONS AND RECOMMENDATIONS	11
GLOSSARY		12
CONVERSION	FACTORS	13
REFERENCES		15
DISTRIBUTION	I	16
APPENDICES		
APPENDIX A	- AIRFIELD LAYOUT PLAN	A-1
APPENDIX E	B - CONSTRUCTION HISTORY	B-1
APPENDIX (C - CORE AND TEST LOCATIONS	C-1
APPENDIX I	- CONDITION SURVEY	D -1
APPENDIX I	E - SUMMARY OF PHYSICAL PROPERTY DATA AND LABORATORY TEST RESULTS	E-1
APPENDIX I	F - NOT USED	
APPENDIX (G - RELATED INFORMATION	G-1

this page intentionally left blank

SECTION I: INTRODUCTION

A. Scope

1. At the request of the 302 AW (AFRES) a pavement evaluation team from HQ Air Force Civil Engineer Support Agency (HQ AFCESA) did a partial evaluation of the Pueblo, CO municipal airport. The objective of the evaluation was to determine if the now closed Runway 12/30 is suitable for C-130 assault operations. The evaluation was done on 5-7 April 94. The report uses several appendices to easily report the vast amount of data gathered. The following list describes each appendix.

Appendix	<u>Description</u>
A	Airfield Layout Plan: The drawings depict the airfield's pavement features, and primary pavements.
В	Construction History: This is an updated list showing the construction history for the evaluated features.
С	Core and Test Locations: A drawing of the core extraction locations. It shows core thicknesses, Portland Cement Concrete (PCC) flexural strengths, Electronic Cone Penetrometer (ECP), and Dynamic Cone Penetrometer (DCP) results.
D	Condition Survey: A drawing of feature surface condition ratings. These ratings are a qualitative assessment based upon visual observations. The rating scale is the same as used in AFR 93-5 (Reference 1).
E	Summary of Physical Property Data and Laboratory Test Results: A tabulation of physical properties of each pavement feature evaluated. Included are feature dimensions, material types, thicknesses of layers, and engineering properties.
F	Allowable Gross Loads (AGLs) and Pavement Classification Numbers (PCNs): Not Used.
G	Related Information: Contains climatic data.

SECTION II. BACKGROUND DATA

A. General Description of Airfield

- 1. Pueblo Airport is located five miles east of Pueblo, CO. It is approximately 45 miles from the Rocky Mountains. The airfield sits on an elevated shelf on the north side of the Arkansas River valley. Lowlands of the river adjoin the site immediately to the south, with elevated ridges extending northwest-southeast through the northeast corner of the reservation. The original site surface was intercepted by many gullies, washes and several small arroyos. The area immediately east of the airfield is studded with numerous rounded shale mounds varying from low hummocks to hillS approximately twenty feet high. A large arroyo transverses the airfield site boundary from the northeast to the west and south. Alkali springs cause surface and subsurface water to flow around and possibly under the runway.
- 2. The airport was constructed for B-24 operations during August September 1943. Runway 12/30 was designed for a 60,000 pound wheel load using a 12 inch stabilized river run gravel base course, a 2 inch asphalt stabilized sand, and a 2 inch asphalt concrete wearing surface. All pavements were constructed of sand and gravel obtained from the Arkansas River, to which was added crushed and graded gravel and boulders. (Reference Two)

B. Climatic Data

1. The design freezing index of Pueblo is 736 and the rain rate is 0.485. The soil frost classification for the base is F3, the subbase is F4 and the subgrade classifies as F3 and F4. According to Reference Three, the maximum depth of frost penetration is 36 inches. During severe winters, frost heave is a problem as evident in feature R06A. The freezing period is November through March. The thaw period is March through April. The weather during the evaluation is shown in Table One.

TABLE ONE

WEATHER DURING EVALUATION

Date	Temperature		ture	Weather
	Hi	Lo	Mean	
5 Apr 94	33	20	26	3 inches accumulated snowfall, snowed until 1300, gradual warming with rapid snow melt
6 Apr 94	55	20	37	Clear, dry with calm winds and snow melted
7 Apr 94	55	45	50	Clear, dry with calm winds

C. Drainage

1. The region has a low average annual precipitation of less than 12 inches, but sometimes the rate of accumulation are high. Therefore, provisions for handling storm water are required. The runway is slightly crowned and the shoulders and surrounding terrain slopes to a drain ditch on the south side of the runway and an arroyo on the north side of the runway. The shoulders were improved with gravel, and the surrounding soil is clay with a vegetation cover. Slow moving water is absorbed in the soil prior to reaching the drainage ditches. Some or the core holes penetrated show evidence of soil saturation with water, and the possibility that underground water moves beneath the runway. Dense turf growth combined with dirt and gravel build up at the runway edges inhibits drainage from the runway edges. Consequently, the outside 12 to 24 feet of the runway have severe raveling and potholes


SECTION III: TEST PROCEDURES

A. Field Testing

- 1. Modified destructive testing was accomplished using AFCESA's contingency van shown in Figure One. Core holes were drilled to extract asphalt concrete (AC) and portland cement concrete (PCC) samples. An electronic cone penetrometer (ECP) and a dynamic cone penetrometer (DCP) were use to determine base, subbase CBRs and thickness. The depth to subgrade and its CBR were also determined using these penetrometers. Small aperture CBR tests were done at selected locations. Appendix Page C-2 shows the test locations.
- 2. To do the DCP test, a cone tipped rod is driven through the pavement layers by dropping a weighted hammer from a predetermined height. The test is typically performed to a depth of 4 feet and the depth of penetration per blow is plotted. The plot is correlated to CBR and used to identify soil layer thicknesses.
- 3. The ECP is a instrumented cone attached to a steel shaft. The cone is driven into the ground at a constant rate by a hydraulic ram. The cone tip and sleeve pressure is measured once each second. These pressures are used to determine both the soil type and CBR from correlation curves developed by the Army Corps of Engineers', Waterways Experiment Station, located in Vicksburg, Mississippi. This test is typically done to a depth of seven feet. Core flexural strength and DCP results aid the calculation of allowable gross loads and pavement classification numbers for each pavement feature.

B. Laboratory Testing:

- 1. Split tensile tests are done on the PCC cores, using the Universal Testing Machine (UTM) and in accordance with ASTM C 496-90 "Standard Test Methods for Splitting Tensile Strength of Cylindrical Concrete Specimens." The core tensile strengths convert to flexural strengths using an empirical relationship developed in Reference 4. The "Core and DCP Location Plan" in Appendix C and the "Summary of Physical Property Data" in Appendix E report the flexural strength.
- 2. Laboratory procedures, done in accordance with ASTM's "Standard Test Methods," classified soil samples using the Unified Soil Classification System (USCS) listed in Reference 6. Appendix page E-2 shows the grain size distributions of soils samples taken from this runway.



ELECTRIC CONE PENETROMETER

FIGURE ONE: CONTINGENCY VAN

SECTION IV: METHODOLOGY OF ANALYSIS

A. Physical Property Data:

1. The principal parameters used for determining AGLs are pavement type, thickness, flexural strength (for PCC only), and CBR. Appendix E summarizes these parameters. The failure criterion for rigid pavements limits concrete tensile stress. Flexible pavement failure criterion limits compressive subgrade strain and asphalt concrete tensile strain.

B. Determination of Allowable Gross Loads (AGLs):

- 1. The computer program, GOAPE, calculated the allowable gross loads for each feature. The Army Corps of Engineers' Waterways Experiment Station at Vicksburg, Mississippi developed the computer model. AGLs were reduced 25% for those Features with a condition rating of POOR or worse.
- 2. The traffic designator at the end of each feature number (A, B, or C) indicates the normal type of traffic. "A" designates channelized traffic by fully loaded aircraft. "B" is used for fully loaded, nonchannelized aircraft traffic on areas such as parking aprons. "C" designates less than full aircraft loading, such as occurs on runway interiors where the wing lift reduces the wheel loading. The "B" designator raises AGLs approximately 5 per cent, while the "C" designator raises AGLs 25 per cent. Consider this when comparing AGLs of a feature with "A" traffic to those with "B" or "C" traffic. The AGLs are listed in Tables One and Two

TABLE ONE

AGLs FOR C-130

<u>Feature</u>	<u>Passes</u>	<u>AGL</u>	Overlay for 500 Passes
R03C	< 10	Α	10 inches
R04A	< 10	Α	16 inches
R05A	500	113	
R06A	< 10	Α	6 inches
R07A	< 10	Α	3.5 inches
R08A	25	Α	5.5 inches
R09A	< 20	Α	7 inches
R10A	58	72	3 inches
R11A	not s	uitable for aircraft t	raffic
R12A	1000	+	

Aircraft evaluated at 120,000 gross weight and 500 passes

[&]quot;A" Denotes the lowest possible weight of the C-130 exceeds the AGL for the pavement feature.

[&]quot;+" Denotes the AGL for the pavement feature exceeds the highest possible C-130 gross weight.

TABLE TWO

AGLs FOR C-130 - FROST CONDITIONS

<u>Feature</u>	<u>Passes</u>	<u>AGL</u>	Overlay for 500 Passes
R03C	< 10	Α	16 inches
R04A	< 10	Α	16 inches
R05A	500	113	
R 06 A	< 10	Α	7 inches
R 07 A	< 10	Α	3.5 inches
R08A	25	Α	5.5 inches
R 09 A	< 20	Α	7 inches
R10A	58	72	3.75 inches
RIIA	not s	suitable for aircraft tr	raffic
R12A	1000	+	

Aircraft evaluated at 120,000 gross weight and 500 passes

[&]quot;A" Denotes the lowest possible weight of the C-130 exceeds the AGL for the pavement feature.

[&]quot;+" Denotes the AGL for the pavement feature exceeds the highest possible C-130 gross weight.

SECTION FIVE: PAVEMENT ASSESSMENT

A. General

1. A detailed pavement condition survey was done in accordance with the procedures outlined on AFR 93-5. Overall the runway has FAILED. The asphalt concrete is severely weathered, the binder material is brittle and the aggregate is easily dislodged from the mix. When vehicles turn on the AC, stones are dislodged and tracks left in the pavement. This would be a problem with aircraft turning and tire spinup on landing. In addition, holding brakes at high power setting would likely scrub the pavement surface. The northwest 3000 feet of the runway (Feature R03C) is in such a poor state it doesn't qualify as an aircraft operating surface. The subgrade is very week. In 1990, earth moving equipment used Features R03C and R04A for a haul road. As a result the pavement is severely rutted with associated alligator cracking. The runway is rough with many areas of swell, some posing a hazard to aircraft operations. The runway was full of dense weed growth, which was cleared off by grading in March 94. The weeds still protrude through the cracks and will return. Long term weed control is required. The predominant distresses are block cracking and longitudinal and transverse cracking. Load related distresses have been covered with numerous AC overlays. Feature R01A and R02A were not evaluated.

B. Runway Features

- 1. In general, Feature R03C is unsuitable for aircraft operations. High severity depressions cover one-third of the AC surface (Photo 1). The center one-third of the AC surface is covered with high severity rutting and alligator cracking (Photo 1), caused by fully loaded earth moving equipment using this area as a haul road. The northwestern two-thirds of the feature is covered with dense weed growth. The northwestern 1000 feet of the feature has 3 6 inches of mud covering the north half of the runway. The feature rated FAILED. The cleared portion of this feature is poor shape (Photo 2)
- 2. The predominant distress in Feature R04A is block cracking. On the north side of centerline there are areas of medium to high severity rutting with associated alligator cracking. In this same area, the pavement was destroyed by the earth moving equipment entering and exiting the runway enroute to the borrow pit (Photo 3). The rut shown is 3 4 inches deep. The center one-third of this feature is smooth enough for aircraft operations.
- 3. Seventy-five per cent of Feature R05A is covered with high severity block cracking. Fifteen percent of the feature is covered with alligator cracking, and this area butts up against Feature R06A (Photo 4). This feature has a one inch overlay, indicating this area of alligator cracking extends into the original AC surface. The overlay was probably laid down to cover this cracking. An area of medium severity alligator cracking runs the entire length of the feature along the paving lane joint, 24 feet south of

centerline. The feature is smooth enough for aircraft operations. This feature rated FAILED.

- 4. Transverse and longitudinal cracking predominate in Feature R06A. Three areas of high severity swells make this feature unsafe for aircraft operations (Photos 5 and 7). Two of the swells show indications of frost heave (Photo 6). The swell in Photo 7 is at the edge of a shale stratum about 3 feet below the pavement surface. There isn't any shale under the swell, and water may running off the shale strata and accumulating in the swell area. The AC on the northwestern side of the swell is 10 inches thick, while the AC over the swell is 5 inches. These factors make this section of the runway susceptible to frost heave. This feature rates FAILED. The roughness profile of the runway is shown in Appendix page D-5. The Aeronautical Systems Center/Weapons Range and Airbase Systems Program Office (ASC/VXO) at Eglin AFB, Florida did a surface roughness analysis for this runway using the computer program TAXIG, and the results are shown in Appendix page D-6. In summary, the bumps on this runway will not overstress the C-130 landing gear.
- 5. Feature R08A rated VERY POOR. It is an 1 to 2 inch overlay. The predominant distresses are high severity block, longitudinal and transverse cracking. This area is smooth enough for aircraft operations. The edges of the overlay are badly raveled.
- 6. Features R09A and R10 A are covered with block cracking and areas of high severity depressions (Photo 8). The depressions appear to be caused by pavement raveling due to standing water. These features rated FAILED.
- 7. Feature R11A rated FAILED. It is so badly weathered and deteriorated that it is no longer distinguishable as an AC pavement (Photo 9).
- 8. Feature R12A is an AC over PCC pavement. All PCC joints have reflected through the AC and the AC has 100 per cent coverage of block cracking (Photo10). The PCC pavement did not show evidence of load induced cracks reflecting through the AC layer. However, the core sample taken from this feature showed the PCC to be deteriorating from alkali reactions. This feature rated FAILED. The joint between Feature R11A and R12A has shoving damage and has caused a 2 inch ridge along the entire width of the runway.

CONCLUSIONS AND RECOMMENDATIONS

A. Conclusions

1. The AC pavement on this runway has reached the end of its useful life. It is badly weathered and aircraft operations will cause rapid deterioration of the surface. There will be a constant Foreign Object Damage (FOD) hazard due to loose stones on the runway. Additionally, Runway 26R/08R will have loose stones blown on it from the prop wash, creating a FOD hazard for that runway as well. Vehicular traffic exiting Runway 18/30 onto Runway 26R/08R tracks stones onto Runway 26R/08R. The base and subgrade are structurally weak, so rutting and alligator cracking along the runway centerline will soon manifest themselves. Extensive clearing and cleaning of the runway shoulders and edges will be required to reduce the FOD hazard and fix drainage problem. Finally, high severity swells, some in excess of six inches pose a structural hazard to C-130 aircraft.

B. Recommendations

- 1. To make this runway suitable for assault landing practice its recommended the southeastern 1000 feet north of Runway 26R be designated an overrun. This will provide prop wash FOD protection for Runway 26R. The next 4000 feet should be smoothed and reconstructed. The next 1000 feet should be designated an overrun. The northwestern 3000 feet of this runway should be abandoned because of the very weak subgrade CBR. This portion of the runway requires complete reconstruction to include a new drainage system and subgrade stabilization.
- 2. Finally, there is a 105 feet tall grain elevator at an elevation of 4604 feet above Mean Sea Level (MSL) (elevation of top of elevator is 4709 feet above MSL) located 2000 feet south of the Runway 26R threshold. This elevator is on the Runway 12/30 centerline, and must be evaluated for obstruction clearance criteria before opening Runway 12/30 to assault operations.

GLOSSARY

Allowable Gross Load (AGL) - The maximum aircraft load that can be supported by a pavement feature for a particular number of passes.

<u>Base or Subbase Courses</u> - Natural or processed materials placed on the subgrade beneath the pavement.

<u>Compacted Subgrade</u> - The upper part of the subgrade, which is compacted to a density greater than the portion of the subgrade below.

<u>Feature</u> - A unique portion of the airfield pavement distinguished by traffic area, pavement type, pavement surface thickness and strength, soil layer thicknesses and strengths, construction period, and surface condition.

<u>Frost Evaluation</u> - Pavement evaluation during the frost-melting period, when the pavement load-carrying capacity will be reduced unless protection has been provided against detrimental frost action in underlying soils

<u>Pass</u> - On a runway, the movement of an aircraft over an imaginary line 500 feet down from the approach end. On a taxiway, the movement of an aircraft over an imaginary line connecting an apron with the runway. AFR 93-5, Chapter 2.

<u>Pass Intensity Levels (PIL)</u> - Specific repetitions of aircraft over a pavement feature, regardless of time, that are dependent on aircraft design category. AFR 93-5, Chapter 2.

<u>Pavement Condition Index (PCI)</u> - A numerical indicator between 0 and 100 that reflects the surface operational condition of the pavement. AFR 93-5, Chapter 3.

<u>Subgrade</u> - The natural soil in-place, or fill material, upon which a pavement, base, or subbase course are constructed.

Type A Traffic Areas - Type A Traffic Areas are those pavement facilities that receive the channelized traffic and full design weight of the aircraft. AFM 88-6, Chapter 1.

Type B Traffic Areas - Type B Traffic Areas are considered to be those areas where traffic is more nearly uniform over the full width of the pavement facility, but which receive the full design weight of the aircraft. AFM 88-6, Chapter 1.

<u>Type C Traffic Areas</u> - Type C Traffic Areas are considered to be those on which the volume of traffic is low or the applied weight of the operating aircraft is less than the design weight. AFM 88-6, Chapter 1.

CONVERSION FACTORS

BRITISH TO INTERNATIONAL SYSTEMS (SI) OF UNITS

British units of measurements are used in this report and can be converted to SI (Metric) units as follows:

TO CONVERT	<u>TO</u>	MULTIPLY BY				
LENGTH						
inch (in)	millimetre (mm)	25.400				
inch (in)	metre (m)	0.0254				
foot (feet)	metre (m)	0.305				
yard (yd)	metre (m)	0.915				
mile (mi)	kilometre (km)	1.609				
AREA						
square inch (in ²)	square millimetre (mm ²)	645.2				
square inch (in ²)	square metre (m ²)	0.0006452				
square foot (feet ²)	square metre (m ²)	0.093				
square yard (yd ²)	square metre (m ²)	0.8361				
square mile (mi ²)	square kilometres (km ²)	2.59				
acres	square kilometres (km ²)	0.004046				
VOLUME						
cubic inch (in ³)	cubic millimetre (mm ³)	16487.0				
cubic foot (feet ³)	cubic metre (m ³)	0.028				
cubic yard (yd3)	cubic metre (m ³)	0.7646				
MASS						
pound (lb)	kilogram (kg)	0.454				
FORCE						
pound (lb f)	Newton (n)	4.448				
kip (1000 lb f)	kilogram (kg)	453.6				
STRESS		4.005				
(psi)	nch kilo Pascals (kPa)	6.895				
	UBGRADE REACTION (I	(-VALUE)				
pounds per square inch kilo Pascals per per inch (psi/in) millimetre (kPa/mm) 0.2715						

DEGREES
Degrees Fahrenheit(°F)
(F°-32) degrees Celsius (°C)

5/9

DENSITY
pounds per cubic foot kilogram per cubic
(pounds mass) metre (kg/m³)

16.052

REFERENCES


- 1. AFR 93-5, <u>Procedures for US Army and US Air Force Airfield Condition Surveys</u>, Jul 1989.
- 2 Pavement Evaluation Report, Pueblo Airfield, Pueblo, Colorado, USCEC TL725.3, U. S. Engineer Department, Missouri River Division, 18 January 1942
- 3. AFM 88-24/TM 5-818-3, Chapter 4, <u>Pavement Evaluation for Frost Conditions</u>", Departments of the Army and Air Force, December 1966.
- 4. Hammitt, G. M. III, Concrete Strength Relationships, Research Paper, Texas A & M University, College Station, Texas, December 1971.
- 5. AFM 89-3, Materials Testing, August 1987.


DISTRIBUTION

302 OSF/DOO	5
295 Dover St, Suite 104	
Peterson AFB, CO 80914-8320	
HQ AFRES/CEOM	2
155 2nd St	
Robbins AFB, GA 31098-1635	
Pueblo Memorial Airport	2
Attn: Mr Chamberlin, Airport Superintendent	
31201 Bryan Circle	
Pueblo, CO 81001	
HQ AMC/CESF	4
507 A Street	
Scott AFB IL 62225-5022	
AFIT/CEE	1
2950 P Street	
Wright-Patterson AFB OH 45433-7765	
DMA Aerospace Center	2
Attn: Air Information Library	
3200 South Second Street	
St Louis AFS, MO 63118-3399	
ANGRC/CEEC	1
3430 2nd Street N.E.	
Minot ND 58701	
NAVFAC Division	1
Attn: 04B1	
200 Stovall Street	
Alexandria VA 22332-2300	
USACE	4
Transportation Systems Center of Mandatory Expertise	
P.O. Box 103, Downtown Station	
Omaha NE 68101-0103	
USA-WES-GP	2
3909 Halls Ferry Road	
Vicksburg MS 39180-6199	

USA-CRREL-EG 72 Lyme Road	2
Hanover NH 03755-1290	
USA-CERL-FOM	2
P.O. Box 4005	
Champaign IL 61820-1305	
HQ AFCESA/TIC	1
139 Barnes Dr, Suite 1	
Tyndall AFB, FL 32403-5319	
Defense Technical Information	2
Attn: DTIC-FDAC	
Cameron Station	
Alexandria VA 22304-6145	
HQ AFCESA/DMP	15
139 Barnes Dr, Suite 1	
Tyndall AFB FL 32403-5319	

This page intentionally left blank.








CONSTRUCTION HISTORY

<u>Feature</u>	Description	Type	<u>Date</u>	Remarks
R02A	Runway 12	PCC	1943	Original Construction
R03C	Runway 12	AC AC	1943 1967-70	Original Construction Overlay
R04A	Runway 12	AC AC	1943 1967-70	Original Construction Overlay
R05A	Runway 12	AC AC	1943 1967-70	Original Construction Overlay
R06A	Runway 12	AC AC	1943 1967-70	Original Construction Overlay
R07A	Runway 12/30	AC AC	1943 1967-70	Original Construction Overlay
R08A	Runway 12/30	AC	1943	Original Construction over fill
		AC	After 1970	Overlay
R09A	Runway 12/30	AC	1967-70	Overlay
R10A	Runway 30	AC	1943	Original Construction over cut
R11A	Runway 30	AC	1943	Original Construction
R12A	Approach end Runway 12	PCC AC	1943 1967-70	Original Construction Overlay

This page intentionally left blank.








A42 A38 A35 A36 X²² X^{16} ∆32 X24 X_{19} X^{17} ×23 \(\int_{13}^{21} \) A39 X¹⁵ X^{25} X 12 X¹⁸ X²⁰ X^{14} Ą41


FIELD TEST RESULTS FROM US ENGINEER DEPARTMENT DATED: 18 JAN 44

437

ĄJ

NUMBER	DEPTH (IN FEET)	# CLAY	* SILT	LIQUID LIMIT	PLASTIC INDEX
A2	1.3 - 1.6 1.6 - 9.0	-	-	-	-
A 23	1.6 - 2.2	42	4.3	45	26
	2.2 - 2.8	44	37	46	26
A 24	1.0 - 1.9	42	46	47	21
	1.9 - 2.5	55	41	49	27
	2.5 - 3.5	42	48	46	26
A 30	0.0 - 6.0	36	53	4.3	22
	6.0 - 9.0	38	43	35	18
A 31	0.0 - 2.0	63	31	46	30
	2.0 - 5.0	47	43	47	28
A 32	1.5 ~ 2.3	48	44	41	23
	2.3 ~ 2.9	50	45	49	28
	2.9 ~	-	-	-	-
A 33	0.5 -	-	-	-	-
A 34	1.0 ~	-	-	-	-
A 35	0.8 ~ 2.2 2.2 ~	44	44	42	23
A 36	1.0 ~ 1.6 1.6 ~	45 -	37 -	39	22
A 37	0.0 - 3.J J.J -	44	42	40	22
A 38	0.0 - 3.0	42	39	37	21
	3.0 -	44	34	39	22
A 39	1.7 - 2.6	35	51	34	17
	2.6 - 3.2	25	66	39	21
A 41	0.9 - 1.8	26	39	32	14
	1.8 - 2.4	32	38	35	18
A 42	0.0 - 2.3 2.3 -	-	-	-	-





ENGINEER DEPARTMENT DATED: 18 JAN 44

# CAY	* SILT	UQUID LIMIT	PLASTIC INDEX	SOIL CLASS
	-	-	-	ML CL
44	4.3 37	45 46	26 26	Cr Cr
42 42	46 41 48	47 49 46	21 27 26	Cr Cr Cr
36 3 8	53 43	4.J 35	22 18	Cr Cr
63 47	31 43	46 47	30 28	Cr Cr
48 56	44 46 -	41 49 -	23 28 -	CL CH SHALE
-	-	-	•	SHALE
-	-	-		SHALE
44	44	42 -	23 -	CL SHALE
45	37	39 -	22	CL SHALE
44	42	40	22	CL SHALE
42 44	39 34	37 39	21 22	ci ci
35 25	51 66	34 39	17 21	g
26 32	39 38	32 35	14 18	ದ್ದ
-	-	-	-	SHAFE

1000 250 375 125 GRAPHIC SCALE IN METERS

GRAPHIC SCALE IN FEET GRAPHIC SCALE IN METERS

LEGEND

- X ELECTRONIC CONE PENETROMETER (ECP) TEST LOCATION
- SMALL APERATURE FIELD COR TEST
- DYNAMIC CONE PENETROMETER (DCP) TEST LOCATION
- FIELD TEST DATA LOCATION REFERENCED FROM OLD US ENGINEER DEPARTMENT DATED JANUARY 18, 1944

NOT EVALUATED


UNITED STATES AIR FORCE
CIVIL ENGINEER SUPPORT AGENCY
TYNDALL AIR FORCE BASE, FLORIDA

TEST LOCATIONS

PUEBLO, COLORADO

WALROND MAY 1994 APPENDOX C C-2

R 03 C



DEPTH TY C (in) MATE

6.0 A


12.0 S

18.0 C

30.0 C


36.0 SH

R 08 A





R 10 A



R 05 A

CORE HOLE # 32																	
DEPTH	TYPE OF	С	CBR FROM DYNAMIC CONE PENTROMETER														
(in)	MATERIAL	<u> -</u>	2	۸ ا	7	4 () (_	,			25	30		20		S S
_	AC																
6.0								П									
12.0	GP-GM									-		+	1				
18.0-							+	\coprod	+				+	_	+-	\dashv	+
	CL						\perp		1	_<			_	_	$oldsymbol{\perp}$	Ц	Щ
24.0—			I											+	\dagger		++
30.0—	GC																
36.0—																	
42.0—	-	[
48.0													\perp				

NOTES:

1. MAXIMUM CORE PENETRATION IS 48 INCHES BELOW PAVEMENT SURFACE.


UNITED STATES AIR FORCE
CML ENGINEER SUPPORT AGENCY
TYNDALL AIR FORCE BASE, FLORIDA


CORE HOLE/TEST LOCATION
CROSS SECTIONS

PUEBLO, COLORADO

	DIGINGER WALKOND	MAY 1994	APPENDIX C
C-3	TIOWELL	NONE	SHEET 3 OF 3









GRAPHIC SCALE IN FEET

500 0 500 1000 1500

HORZ:

GRAPHIC SCALE IN FEET

500 0 125 250 375 500

GRAPHIC SCALE IN METERS

GRAPHIC SCALE IN FEET

100 0 100 200 300

VERT: 100 0 25 50 75 100

GRAPHIC SCALE IN METERS

LEGEND

NOT EVALUATED

(NOT USED)

(NOT USED)

(NOT USED)

(NOT USED)

(NOT USED)

(NOT USED)

FAIR

(NOT USED)

POOR

VERY POOR

FAILED

UNITED STATES AIR FORCE CIVIL ENGINEER SUPPORT AGENCY TYNDALL AIR FORCE BASE, FLORIDA


CONDITION SURVEY


PUEBLO, COLORADO

WALFOND MAY 1994 APPENDIX D


D-1 TIDWELL CHAPHIC SHEET 1 OF 8


1 2 3 4 5 6 7











LEGEND

25 PHOTOGRAPH LOCATION, DIRECTION AND NUMBER

UNITED STATES AIR FORCE
CML ENGINEER SUPPORT AGENT
TYNDALL AIR FORCE BASE, FLORE

PHOTOGRAPH LOCATION

	WALROND	MAY 1994	APPENDOX
D-2	NOWELL.	GRAPHIC	SHEET 2




PHOTO 1 : GENERAL CONDITION OF FEATURE RO3C (DAMAGE CAUSED BY EARTH MOVING EQUIPMENT).

PHOTO 2 : TYPICAL VIEW OF CLEARED PORTION OF FE





PHOTO 4 : HIGH SEVERITY ALLIGATOR CRACKING (FEATURE ROSA).

PHOTO 5 : FOUR INCH SWELL ACCROSS ENTIRE WID

 $^{\rm E}$ $^{\rm RO3C}_{\rm CAL}$ view of cleared portion of feature rosc.

PHOTO 3 ; HIGH SEVERITY RUTTING IN FEATURE RO4A.



IF PAVEN INCH SWELL ACCROSS ENTIRE WIDTH OF PAVEMENT (FEATURE ROBA).

UNITED STATES AIR FORCE
CML ENGINEER SUPPORT AGENT
TYNDALL AIR FORCE BASE, FLORI

PHOTOGRAPHS

	WALROND	MAY 1994	APPENDIX
) –3	TIDWELL	NONE	SHEET 3




PHOTO 6 : AREA OF HEAVED PAVEMENT IN FEATURE ROGA.

PHOTO 7 ; SIX INCH SWELL ACROSS ENTIRE WIDTH BOUNDARY BETWEEN ROSA AND RO7A.





PHOTO 9 ; FAILED PAVEMENT IN FEATURE R11A.


PHOTO 10; JOINT REFLECTION CRACKING AND BLC FEATURE R12A.



CH SWELL ACROSS ENTIRE WIDTH OF PAVEMENT NEAR ARY BETWEEN RO6A AND RO7A.



<u>PHOTO 8</u>: TYPICAL BLOCK, LONGITUDINAL AND TRANSVERSE CRACKING (FEATURE P.10A).





REFLECTION CRACKING AND BLOCK CRACKING TYPICAL IN IPE P124


UNITED STATES AIR FORCE CML ENGINEER SUPPORT AGENCY TYNDALL AIR FORCE BASE, FLORIDA

PHOTOGRAPHS

		MAY 1994	APPENDIX D
D-4	TIDWELL	NONE	SHEET 4 OF










This page intentionally left blank.


	٦	ACILITY			Ш	RLAY PAVEMEN	┕		PAVEMENT			BASE			SUBBASE	Γ	CHRCDANE	No.
FEAT		167H	MOTH (ft)	COND	THICK (in)	DESCRP	1000E	THICK (in)	DESCRE	1000E	THICK	DECEBB	1000E	THICK	DECCEB	1000E	000000	1000E
2	AVPUOTU 35-700		140	<u> </u>	1	ļ		2	PCC (ANGLED LENGTH)		01	CLAYEY SAND (SC)	75				LEAN CLAY (CL)	790 290
8	RO3A NA-SE RUMAAY	2500	3	140 FAIL				4.5	AC		13.0	W/G GRVL W/CLAY & SAND	R				LEAN CLAY (CL)	
8	NA-SE RUPAANY	8	\$	140 FAIL				6.0	A C		10.01	(GW-GC) GRAVEL W/SILT (GM)	45				SANDY CLAY (SC)	
ROSA	NAJ-SE Rumany	388	140	140 FAIL				5.0	V C		12.0	P/G GRVL W/SILT & SAND	12	6.0	LEAN CLAY W/SAND	2	CLAYEY GRAVEL W/SAND	30
3	ROGA NA-SE RUMAAY	972	94	140 FAIL				7.00	AC		0.11	P/G SAND W/SILT & GRAVEL	9	9.0	CLA CLA CLA	2	SHALE	100
R07A	MAL-SE RUPABAY	610	140	140 FAIL				4.5	AC		12.0	POORLY GRADED GRAVEL GRAVEL	F	22.0	SANDY SILT (SM)	30	SHALE	100
3	RUMARY .	630	140	VERY POOR				6.0	AC		11.0	CLAYEY SAND W/GRAVEL	12/2	0-24.0	LEAN CLAY W/SAND	2.5	SHALE	65
8	NA-SE RUMAAY	1745	2 8	55 FAIL				6.0	AC		12.0	POORLY GRADED GRAVEL	12				LEAN CLAY (CL)	2
8 10 10	NA-SE RUMAY	1745	140	140 FAIL				7.0	AC		7.0	CLAYEY SAND W/GRAVEL	31	3.0 +	LEAN CLAY W/SAND	4	SHALE	70
A11A	NA-SE RUNAAY	141	140	140 FAIL				6.5	AC		7.0	CLAYEY SAND W/GRAVEL	31	3.0 +	LEAN CLAY W/SAND	4	SHALE	20
2	R12A M4-SE RIMMAY		140	140 FAIL	1.25	AC (ANGLED LENGTH)		10.0	PCC ALKALINE REACTION TOP 5"		5.0	SANDY CLAY (SC)	140				CLAY (CL)	20

This page intentionally left blank.









GRAIN SIZE DISTRIBUTION GRAPH - AGGREGATE GRADING CHART PUEBLO US STANDARO SIEVES 30 50 60 140 200 20 RETAINED PASSING 40 PERCENT 30 30 20 10 50 20 100 50 20 PERCENT 70 100 50 10 0.5 0.1 0.05 0.01 0.005 GRAIN SIZE IN MILLIMETERS CORE HOLE LIQUID PLASTIC PLASTIC FROST | LIMIT | LIMIT | INDEX | GROUP MUNSELL / REMARKS GROUP SYMBOL LAYER DEPTH C: 2.73 SC BC 5.5 2.72 CLAYEY SAND W/ GRAVEL 31 14.5 12.6 F2 32 BC 4.75 NT NP NP NP \$1 GP-GM POOR GRAD GRAVL W/SILT/SAND 33 вс 4.25 NT 31.3 15.8 15.5 F1 GW-GC WELL GRAD GRAVL W/CLAY/SAND


JTION

15.8

UTION

PLAST

19.5



UNITED STATES AIR FORCE CNIL ENGINEER SUPPORT AGE TYNDALL AIR FORCE BASE, FLO

LABORATORY TEST RES

	WALROND	MAY 1994	APPDIO
E-2	TIDWELL,	NONE	SHEET !

TAB A

PUEBLO MEMORIAL AIRPORT

TOPOGRAPHY: Pueblo Memorial Airport is located 6 miles east of town, having moved to this location June 1, 1954. Pueblo is located at the junction of the Arkansas and Fountain Rivers, about 40 miles east-southeast of the point where the Arkansas River leaves the mountains through the Royal Gorge. The mountains extend to within 25 miles of the city to the southwest and within about 35 miles to the northwest. The surrounding country consists of rolling plains, broken by arroyos (usually dry); it is generally treeless and is covered sparsely with bunchgrass and cacti. The Arkansas River flows eastward about 2 miles south of the airport, which is approximately 45 feet above the river bed on rolling table land.

The mountain ranges to the west run generally north and south; about 60 miles north of Pueblo the Palmer Lake Divide extends east from the main range (this range has altitudes above 8000 feet). The ground slopes upward from Pueblo in every direction except the east and southeast.

VISIBILITY: Most of the smoke sources are in the western quadrant, thus all reductions in visibility occur with winds from that direction. Light and moderate fogs are most frequent during December. Radiation fog seldom occurs and when it does it is of short duration. The most likely time for it to form is between midnight and sunrise following precipitation on the previous day; it usually dissipates 2 or 3 hours after sunrise.

Dust storms cause visibility restrictions primarily during January, February and March. They are caused by high winds from the western quadrant which pick up dry surface soil and fine sand. Before January and after March there is normally enough surface vegetation to protect the soil and dust storms do not occur except with the most severe winds.

SEVERE WEATHER: The thunderstorm season is from late April through September. Practically all thunderstorms occur during the afternoon hours, thunderstoms occurring at night are rare and thunderstoms occurring after midnight are extremely rare. Thunderstorms usually form over the mountains during the morning hours and move over the plains during the afternoon. Hail may accompany these storms during any month, but is much more frequent during the early part of the thunderstom season (the maximum likelihood of hail occurrence is May). The area north of the Arkansas River and the section just east of the city seem far more likely to get severe hail in such storms than the southwest part of the city. Thunderstorms that form over the mountains to the northwest of Pueblo are more likely to move into the vicinity of Pueblo than those that form in the southwest.